County: Lake Traverse NW1/4 Section: 17 FILED FOR RECOLEAND Surveying Township: 37 North 27 PAGE 29 Range: 9 West Parcel No.: 45-03-17-153-009.000-025 2014 083112 1450 119th Street 2014 DEC 29 PH 3: 31 Whiting, Indiana 46394 MICHAEL O. SROWN (219) 659-4000 Plat of Survey
2014-083112 Name of Owner: Mary Ellen Robinson 60' Address of Property: 2829 White Oak Avenue, Whiting, IN. 46394 Description of Property: Lot 35, and the South 10 feet of Lot 36, in Block 7, in Davidson's 7th Addition to Whiting, as per plat thereof SCALE: 1" = 20'-00"recorded in Plat Book 2 page 76, in the Office of the Recorder of Lake County, Indiana. 66,00 FILED DEC 2 9 2014 N.15' LOT 36 & S.21' LOT 37 45-03-17-153-008.000-025 PEGGY HOLINGA KATONA LAKE COUNTY AUDITOR 1 STORY FRAME FRAME HOUSE 3.7'N N 89'16'30" Ex S.10 LOT 36 GARAGE Z 回 onc. walk 1 STORY FRAME HOUSE LOT 35 S 89°16'30" 100.00' BLDG. 1 STORY BLD 5.4's. BRICK HOUSE 5.8' 3.3'S. 3.5'S FRAME GARAGE Surveyor's Report This survey was conducted as a retracement survey in accordance with 865 IAC 1-12 (Rule LOT 33 & 34 45-03-17-153-010.000-025 The following information was used for reference in the preparation of this survey.

1. The recorded plat of Davidson's 7th Addition to Whiting, as per plat thereof, recorded in Plat Book 2 page 76, in the Office of the Recorder of Lake County, Indiana. 2. The Whiting quarter section map of the Northwest 1/4 of Section 17, Township 37 North, Range 9 West of the 2nd Principal Meridian. 3. A Plat of Survey by Steve W. Manich dated August 21, 1956 of Lots 30 and 31, in Block 7, in said Davidson's 7th Addition to Whiting. 4. No title commitment was provided for the completion of this survey. Availability and Condition of Reference Monuments 1. A 1in dia. pipe was found near the Southeast corner of Lot 45, in Block 7, in said Davidson's 7th Addition to Whiting, near grade and used for reference. 2. A 5/8in dia. rebar was found near the Northwest corner of the South 1/2 of Lot 7, in Block 7, in said Davidson's 7th Addition to Whiting, near grade and used for reference. 3. A 5/8in dia. rebar was found disturbed near the Northeast corner of the South 21' of Lot 37, in Block 7, in said Davidson's 7th Addition to Whiting, near grade and used for reference. 4. A 1in dia. pipe was found near the Northwest corner of the South 20' of Lot 15, in Block 7, in said Davidson's 7th Addition to Whiting, near grade and used for reference. 5. A 1in dia. pipe was found near the Southeast corner of the North 4 feet of Lot 29, in Block 7, in said Davidson's 7th Addition to Whiting, near grade and used for reference. 6. A notch at back of walk was found at the Northwest corner of Lot 44, in Block 6, in said Davidson's 7th Addition to Whiting, at grade and used for reference. 7. A 1in dia. pipe with cap labeled "Dillon" was found at the Southwest corner of Lot 44, in Block 6, in said Davidson's 7th Addition to Whiting, at grade and used for control. 8. A 5/8in dia. rebar was found at the Northwest corner of Lot 41, in Block 6, in said Davidson's 7th Addition to Whiting, near grade and used for control. 9. A 5/8in dia. rebar was found at near the Northwest corner of Lot 26, in Block 6, in said Davidson's 7th Addition to Whiting, near grade and used for reference. Occupation or Possession Lines Occupation and possession lines appear consistent with the record description other than as noted on the hereon drawn plat. Clarity or Ambiguity of the Record Description No apparent ambiguity was observed in the record description or the adjoiners' descriptions with the record description. No apparent ambiguity was observed in the record lines or the adjoiners' lines with the record lines based upon description. The Relative Positional Accuracy of the Measurements This survey meets the requirements of a(n) Suburban Survey for which the acceptable relative positional accuracy is 0.13 feet plus 100 parts per million. **Basis of Bearings** The basis of bearings for this survey is assumed. NO DIMENSIONS SHOULD BE ASSUMED BY SCALE MEASUREMENT UPON THE PLAT NOTE - Contractors or builders should be notified to carefully test and compare on the ground the 0 points, measurements, etc., as noted in this certificate, with the stakes, points, etc., given on the property, before building on the same, and AT ONCE report any seeming or apparent difference between the same to the Surveyor, that misunderstanding, displacement of points, etc., may be corrected before damage is done. Prepared for: MARY ELLEN ROBINSON Job No.<u>14-0048</u> Surveyor's Certificate I, Frank A. Walsko, hereby certify that this survey was performed under my direction in accordance with 865 IAC 1-12 (Rule 12) and to the best of my knowledge, information and belief, the plat hereon drawn is a true and accurate representation of said survey. Given under my hand and seal this 29th day of December, 2014. STREET 129th STATE OF -NOTCH = CHISELED NOTCH SET • MAG SET = MAGNETIC SURVEY NAIL SET ●RS = 5/8" DIA. REBAR SET W/CAP Frank A. Walsko, Registered Land Surveyor, "FRANK WALSKO LS20700105" State of Indiana, No. LS20700105 DATE OF LAST FIELDWORK = December 27, 2014