Engineers and Surveyors

Merri Fax:



Plat of Survey


The West 600 feet of the North 515 feet of the Northwest Quarter of the Southwest Quarter of Section 17, Township 34 North, Range 8 West of the 2ng Principal Meridian lying North of Cedar Lake Road, containing 6 acres, more of less.

18.DG CK 5337 2003 078414

FILED

JUL 2 9 2003

STEPHEN R. STIGLICH



Surveyor's Report

In accordance with title 865 of the Indiana Administrative Code, Article 1, Rule 12, Section 12, the Surveyor shall report his opinions of the causes and amounts of any positional uncertainty in the lines and corners found or established in any original or retracement survey resulting from the following:

A) Availability and condition of reference monuments:
Northwest, Northeast, Southeast, Southwest & South Quarter corner Section corner per record of Lake

- C) Ambiguities and Discrepancies in the locations of structures: None- vocant land
- theoretical uncertainty of measurements.
- This survey was performed in accordance with the specifications for a class 'c' boundary survey as defined under 865 iao 1-12-7e such that the theoretical uncertainty of any corner position shall be within the limits of 0.50 feet, more or less.

Record Documents

Lake County Surveyor's Office Section corner info.
Sidwell maps of Sections 17-34-8 and 20-34-8.
Survey of St. Anthony's Home, Section 17-34-8, by Samuel Brownsten dated May 13, 1961.
Road Records Commissioner's Book 10, page 27 &29; Book 3, order 8, page 12; Book 3, order 85, page 5; Book 3, order 350, page 12; Book 39, order 65, page 28.
Quit Claim Deeds #2003-003363; #96060851; #2002-017831; #2001-031099

Corporate Warranty Deed #950228 Warranty Deeds #907498; #2003-045323



STATE OF INDIANA SS

Plat of Survey

In-Pact/ Herb Grulke 12300 Marshall Street Crown Point, Indiana 46307 (219) 662-1905