F84000

KRULL & SON

ENGINEERS AND SURVEYORS

PLAT OF SURVEY

ESTABLISHED 1914 P.O. BOX 422 206 MAIN STREET HOBART, INDIANA 46342 OFFICE PHONE 219947-2568

2003 111470

BOOK 010 PAGE 45

FILED FOR RECORD 2003 OCT 16 PM 2: 27



ROBERT A. KRULL

STATE OF INDREG ENGINEER INC. 10516

FILED

OCT 15 2003 STEPHEN R. STIGLICH

LAKE COUNTY AUDITOR

DESCRIPTION OF PROPERTY: Part of the SE 1/4 of Section 2, Township 34 North, Range 8 West of the 2nd P.M. in Lake County, Indiana, described as follows: Beginning at a point on the South line of the SE 1/4 of said Section

2 being 1747.27 feet West of the Southeast corner thereof; thence continuing along the said South line South 87°40'47" West, 178.18 feet; thence North 02°19'13" West, 30.00 feet; thence North 00°01'08" West, 145.24 feet; thence North 85°43'58" East, 154.53 feet; thence North 00°59'13" West, 114.33 feet; thence North 89°17'14" East, 47.96 feet; thence South 00°59'10" East, 79.02 feet; thence South 15°19'09" West, 82.43 feet; thence South 00°51'38" West, 105.94 feet; thence South 02°19'13" East, 30.00 feet to the point of beginning, containing 0.860 acres more or less.

> 2003-111470 2003 Oct 16 10-45 SURVEYOR'S REPORT In accordance with Title 865, Article 1.0, Chapter 12, Section 1 through 34 of the Auo: 484

The following monuments were used for this survey:

this survey as a result of:

1. A Mag Nail was found and used at the Southeast corner of Section 2 which agrees with surveys in Sections 1 and 2 by Krull And Son.

regarding the various uncertainties in the location of the lines and corners established on

2. A Lake County monument was found and used at the Northeast corner of Section 2.

3. A Lake County monument was found and used at the Southwest corner of Section 2.


Availability and condition of reference monuments: The monuments were in good condition and appeared undisturbed and were found at or near grade.

Indiana Administrative Code, the following observations and opinions are submitted

Uncertainties resulting from occupation lines: No apparent uncertainties in possession were observed.

Discrepancies due to record descriptions: No apparent uncertainties resulted from the record descri

The Theoretical Uncertainty (due to random errors in measurements) of the subject tract established this survey is within the specifications for a Class C Survey 0.50 feet as defined in IAC 865.



EXPLANATIONS

NO DIMENSIONS SHOULD BE ASSUMED BY SCALE MEASUREMENTS UPON THE PLAT NOTE - CONTRACTORS OR BUILDERS SHOULD BE NOTIFIED TO CAREFULLY TEST AND COMPARE ON THE GROUND THE POINTS, MEASUREMENTS, ECT., AS NOTED IN THIS CERTIFICATE, WITH THE STAKES, POINTS, ECT., GIVEN ON THE PROPERTY, BEFORE BUILDING ON THE SAME, AND AT ONCE REPORT ANY SEEMING OR APPARENT DIFFERENCE BETWEEN THE SAME TO THE SURVEYOR, THAT MISUNDERSTANDING, DISPLACEMENT OF POINTS, ECT., MAY BE CORRECTED BEFORE DAMAGE IS DONE.

PT. SE 1/4 SEC. 2-34-8

FIELD BOOK NO.

ORDERED BY

Notes

Gerald Black

DISK: K350 FILE: 02-245A.*

No. 10516 SCALE: 1" = 30'-00"

STATE OF INDIANA)
COUNTY OF LAKE)

April 8, 2002 HOBART, INDIANA

THIS IS TO CERTIFY THAT I HAVE SURVEYED THE ABOVE DESCRIBED PROPERTY ACCORDING TO THE OFFICIAL RECORDS AND THAT THE PLAT HEREON DRAWN CORRECTLY REPRESENTS SAID

2612 E 189TH AVE JOSH HEAVNER CROWN POINT, IN 46307

TWP34N

· 🗲 1

SE. CORNER