MARIELL & SON WILLIAM J. KRULL ROBERT A. KRULL REG. ENGINEER No. 235 REG. ENGINEER No. 3892 REG. SURVEYOR No. 10516 KEVIN A. KRULL 17 PAGE 25 **REG. SURVEYOR No. 20100075** ENGINEERS AND SURVEYORS 2007 JUN | 8 AM | 1: 45 ESTABLISHED 1914 000296 2007 049447 FILED P.O. BOX 422
206 MAIN STREET
HOBART, INDIANA 46942
OFFICE PHONE 219-947-2568 RECORDER PLAT OF SURVEY JUN 18 2007 PEGGY HOLINGA KATONA LAKE COUNTY AUDITOR | SUMMIT NORTH LINE SW 1/4 SEC.4 - TWP34N - R8W7 S 89'32'42" E 2656.92' NW. CORNER SW1/4 SEC.4 NE. CORNER SW1/4 SEC.4 DESCRIPTION OF PROPERTY: The West 344 feet of the North 1/2 of the SW 1/4 of the SW 1/4 of Section 4, Township 34 North, Range 8 West of the 2nd P.M. in Lake County, Indiana. 2007 049447 MONITOR STREET
NORTH LINE SW 1/4 SW 1/4 SEC.4 - TWP34N - R8W7 SURVEYOR'S REPORT In accordance with Title 865, Article 1.0, Chapter 12, Section 1 through 34 of the Indiana Administrative Code, the following observations and opinions are submitted regarding the various uncertainties in the location of the lines and corners established on this survey as a result of: The following documents were used in the course of this survey: 1. A Plat of Survey by Krull and Son, dated August 21, 1957, of two parcels in the North end of the hereon described parcel. 2. The recorded subdivision plat of Morning Sun Homes. 5.213 Ac. 3. This survey was performed without the benefit of a Title Commitment. Possible easements may exist as evidenced from field gt 0 The following monuments were used for this survey: 1. The county monument at the Northeast corner of Section 4. 3'42" E 2649.54' 4 SEC.4 – TWP34N The county monument at the Southeast corner of Section 4. The county monument at the Northwest corner of Section 4. 4. A gear bolt at the Southwest corner of Section 4 set by Krull and Son on May 25, 2005 using surveys in Young's Second Addition to Crown Point. EXISTING BUIDLING 5. An iron pipe ant the West 1/4 corner of Section 4 which was used in numerous old surveys. 6. A mag nail at the center of Sec Availability and condition of reference monuments: The monuments were in good condition and appeared undisturbed and LINE EXISTING GREENHOUSE were found at or near grade. Uncertainties resulting from occupation lines: Apparent uncertainties in possession were observed. Fence lines deviated from deed lines by as much as 6.4 feet as shown on the hereon Discrepancies due to record descriptions: **EXISTING GREENHOUSE** The description hereon was derived from the parent parcel and the East adjoing parcel which was cut out of the parent parcel. The parent parcel reads the North 1/2 of the SW 1/4 of the SW 1/4 of Section 4 and the East adjoining parcel reads North 1/2 of the SW 1/4 of the SW 1/4 of Section 4, except the West 344 feet. As evidenced by deeds, the North 140 feet of the West 344 feet was deed off and then deeded back to the owner of the West 344 feet of the North 1/2 of the SW 1/4 of the SW 1/4 **EXISTING GREENHOUSE** of Section 4 which apparently creates two tax parcels. The Relative Positional Accuracy (due to random errors in measurements) of this survey is within that allowable for a Urban Survey (0.07 feet plus 50 ppm) as defined in IAC 865. 30/00, N 89°23'38" W 344.00' SOUTH LINE N 1/2 SW 1/4 SW 1/4 SEC.4 - TWP34N - R8W PORTER STREET NOTE: According to FIRM Community-Panel 180128-0005-C, dated February 12, 1982, the above described parcel is in Zone "C". NOTE: The building and greenhouses were not located per client's request. Their location was derived from arial photography. SW. CORNER SE. CORNER SW1/4 SEC.4 N 89°20'33" W 2644.12' SOUTH LINE SW 1/4 SEC.4 - TWP34N - R8W NORTH STREET NO DIMENSIONS SHOULD BE ASSUMED BY SCALE MEASUREMENTS UPON THE PLAT STATE OF INDIANA) NOTE - CONTRACTORS OR BUILDERS SHOULD BE NOTIFIED TO CAREFULLY TEST AND COMPARE ON THE HOBART, INDIANA November 20, 2006 COUNTY OF LAKE) GROUND THE POINTS, MEASUREMENTS, ETC..., AS NOTED IN THIS CERTIFICATE, WITH THE STAKES, POINTS, ETC... GIVEN ON THE PROPERTY, BEFORE BUILDING ON THE SAME, AND AT ONCE REPORT ANY SEEMING OR APPARENT THIS IS TO CERTIFY THAT I HAVE SURVEYED THE ABOVE DESCRIBED PROPERTY ACCORDING TO DIFFERENCE BETWEEN THE SAME TO THE SURVEYOR, THAT MISUNDERSTANDING, DISPLACEMENT OF POINTS, THE OFFICIAL RECORDS AND THAT THE PLAT HEREON DRAWN CORRECTLY REPRESENTS SAID ETC.., MAY BE CORRECTED BEFORE DAMAGE IS DONE. No. 10516 PT. SW 1/4 SEC. 4-34-8 Notes

SCALE: 1"

= 60'-00'

ORDERED BY Tim Heidbreder