KRULL SURVEYING WILLIAM J. KRULL ROBERT A. KRULL REG. ENGINEER NO. 3092 REG. EURVEYOR NO. 10010 3 4 PAGE 3 2 KEVIN A. KRULL ENGINEERS AND SURVEYORS BOOK ESTABLISHED 1914
1326 GLAKE PARKAVENUE
HOBART, INDIANA 46342
OFFICE PHONE 218-647-2666 STATE OF INDIANA PLAT OF SURVEY LAKE COUNTY 2019-076170 DESCRIPTION OF PROPERTY: Lot 7. Resubdivision of Lots 26, 27, 28, and 28, Palm Gardens, Ualt No. 2, as per plat thereof, recorded in Plat Book 45 page 58; in the Office of the Recorder of Lake County, Indiana and Lot 1, Joe Wegmat Subdivision, as per plat thereof, recorded in Plat Book 42 page 2, in the FILED FOR RECORD MICHAEL B BROWN Office of the Recorder of Lake County, Indiana-2:08 PM 2019 Nov 5 RECORDER HICKEY STREET Document is This Document is the property of OUR the Lake County Recorder! lo N 30.00,00. Ay In accordance with filte 86b, Article 1.0, Chapter 13, Section 1 through 34 of the Indiana Administrative Code, the following observations and symbols are cubmitted regarding the various uncertainties in the location of the index and corners established on this survey as a result of: The menuments were in good condition and appeared undisturbed and were found at or near grade. Uncertainties resulting from ossupation lines;

Apparent uncertainties in presented were observed. Fence lines deviated from the surveyed dead lines by as much as 0.8 of a foot as shown The following documents were used in the course of this curvey:

1. The recorded subdivision plat of Resubdivision of Lots 26, 27, 28, and - BITUMINOUS PAVEMENT 1. The recorded supulmanon plat of newsparished of loss we er, so, was 29, Palm Gerdens, Unit No. 2 prepared by Krull and Son.
2. The recorded subdivision plat of Joe Weghqat Subdivision prepared by Rowland A. Fablan.
3. Provious surreys by Krull and Son in said subdivisions. NOV 05 2019 - CONCRETE Bistrepancies due to feoord documents: Apparent uncertainties resulted from the record documents. The recorded subdivision plat of Joe Wogmet Subdivision propered by Rowland A. Fabian contains numerous computational errors. Iron monuments from previous surveys by Krull and Son in said subdivisions. The Relative Positional Accuracy (due to random errors in measurements) of this survey is within that allowable for a Saburban Survey (0.13 feet plus 100 ppm) as defined in IAC 885. 2. Iron rods shown as set bereon are 5/8 inch rebar, 24 inches long, with JOHN E. PETALAS yollow surveyor identification cap stamped "Krull RLS 20100075". LAKE COUNTY AUDITOR **EXPLANATIONS** NO DIMENSIONE SHOULD BE ASSUMED BY SCALE MEASUREMENTS UPON THE PLAT NOTE - CONTRACTORS OR DULDERS SHOULD BE NOTIFIED TO CAREFULLY TEST AND COMPARE ON THE GROUND THE POINTS, MEASUREMENTS, ETC... AS NOTED IN THIS CERTIFICATE, WITH THE STAKES, POINTS, ETC...

GIVEN ON THE PROPERTY, BEFORE BUILDING ON THE SAME, AND AT ONCE REPORT MY GETMING OR APPARENT DIFFERENCE BETWEEN THE SAME TO THE SURVEYOR, THAT MISUNDERSTANDING, DISPLACEMENT OF POINTS. ETC... MAY BE CORRECTED REFORE DAMAGE IS DONE.

PALM GARDEN UNIT 2 RESUBDINISION CD: K3 FILE: 16-106.* (\Genver\d\Krull Surveying\Work\10-106.dwg) KK

PIELO BOOK NO. Notes Delores Robb PLAT NO. XL-





STATE OF INDIANA) SS:

HOBART, INDIANA June 28, 2018