WILLIAM J. KRULL REG. ENGINEER No. 235 KEVIN A. KRULL **REG. SURVEYOR No. 20100075**

STATE OF IN KRULL & SON

ROBERT A. KRULL REG. ENGINEER No. 3892 REG. SURVEYOR No. 10516

2006 093223

FILEO FOR RECORD 2006 OCT 24 PM 1:43

MICHAEL A. BROWN RECORDER

ENGINEERS AND SURVEYORS ESTABLISHED 1914 P.O. BOX 422 206 MAIN STREET HOBART, INDIANA 46342 OFFICE PHONE 219-947-2568

PLAT OF SURVEY

16 PAGE 08

DESCRIPTION OF PROPERTY:


PARCEL 1: The North 212 feet of that part of the NE 1/4, NE 1/4 Section 32, Township 36 North, Range 7 West of the 2nd P.M. lying Easterly of the Southeasterly right-of-way of the E.J. and E. Railroad. Subject to all public right-of-ways.

PARCEL 2: Part of Section 17, Township 36 North, Range 7 West of the 2nd P.M. in Lake County, Indiana, described as follows: Commencing at the Northeast corner of said NE 1/4; thence North 88°34'40" West, along the North line of said NE 1/4, 42.91 feet to the Southeasterly right-of-way line of the Elgin, Joliet and Eastern Railroad and the point of beginning; thence South 47°03'21" West, along said Southeasterly right-of-way line, 303.10 feet; thence North 42°56'39" West, at right angles to said right-of-way line, 50.00 feet to the center line of said Elgin, Joliet and Eastern Railroad; thence North 47°03'21" East, along said center line, 251.99 feet to the North line of said NE 1/4; thence South 88°34'40" East, along said North line, 71.51 feet to the point of beginning, containing 0.319 acres, more or less.

2006 093223

OCT 2 4 2006

PEGGY HOLINGA KATO LAKE COUNTY AUDITO



2. A Plat of Survey by Krull and Son, dated March 8, 1966, of the hereon surveyed

- The following monuments were used for this survey: 1. The county monument at the Northwest corner of Section 12.
- 2. A Survey Marker at the Northeast corner of Section 12. 3. An iron pipe at the intersection of the East line of said Section 12 and the

Availability and condition of reference monuments: The monuments were in good condition and appeared undisturbed and were found at

railroad South of the surveyed parcel as shown on the hereon drawn plat.

Uncertainties resulting from occupation lines:

or near grade.

A fence line deviated from the South deed line as shown on the hereon drawn plat.

Discrepancies due to record descriptions: No apparent uncertainties resulted from the record descriptions.

The Theoretical Uncertainty (due to random errors in measurements) of the subject tract established this survey is within the specifications for a Class B Survey 0.25 feet as defined in IAC 865.

EXPLANATIONS

NO DIMENSIONS SHOULD BE ASSUMED BY SCALE MEASUREMENTS UPON THE PLAT NOTE - CONTRACTORS OR BUILDERS SHOULD BE NOTIFIED TO CAREFULLY TEST AND COMPARE ON THE GROUND THE POINTS, MEASUREMENTS, ECT., AS NOTED IN THIS CERTIFICATE, WITH THE STAKES, POINTS, ECT., GIVEN ON THE PROPERTY, BEFORE BUILDING ON THE SAME, AND AT ONCE REPORT ANY SEEMING OR APPARENT DIFFERENCE BETWEEN THE SAME TO THE SURVEYOR, THAT MISUNDERSTANDING, DISPLACEMENT OF POINTS, ECT., MAY BE CORRECTED BEFORE DAMAGE IS DONE.

PT. NE 1/4 SEC. 32-36-7

DISK: K763 FILE: 06-2.*

Notes ORDERED BY Ron Sadelack

PLAT NO. XI- 3///

30' SCALE: 1" = 30'-00" STATE OF INDIANA)
COUNTY OF LAKE)

No. 10516

STATE OF

HOBART, INDIANA

March 31, 2006

PA 115

THIS IS TO CERTIFY THAT I HAVE SURVEYED THE ABOVE DESCRIBED PROPERTY ACCORDING TO THE OFFICIAL RECORDS AND THAT THE PLAT HEREON DRAWN CORRECTLY REPRESENTS SAID