REG. SURVEYOR No. 20100075

2014 028164

2014 MAY 16 AM 8: 55

KRULL SURVEYING

ENGINEERS AND SURVEYORS ESTABLISHED 1914

1325 S. LAKE PARK AVENUE HOBART, INDIANA 46342 OFFICE PHONE 219-947-256

PLAT OF SURVEY

NAME OF OWNER: ADDRESS OF PROPERTY: 16712 Mississippi Street, Lowell, Indiana 46356 DESCRIPTION OF PROPERTY: Part of the NE 1/4 of Section 15, Township 33 North, Range 8 West of the 2nd P.M. in Lake County, Indiana, described as follows: Commencing at the Northeast corner of said NE 1/4; thence South 00°51'02" East, along the East line of said NE 1/4, 1584.37 feet to the point of beginning; thence continuing along said East line South 00°51'02" East, 542.23 feet; thence North 89°07'21" West, 335.71 feet; thence North 02°54'33" West, 438.07 feet; thence North 89°11'43" West, 42.41 feet; thence North 00°26'52" West, 101.09 feet; thence South 89°41'06" East, 393.05 feet; to the point of beginning, containing 4.378 acres, more or less.

"SIEGMUND AND KAREN KREBS" DOC. NO. 774099

NE. CORNER NE1/4 SEC.15

ROBERT A. KRULL REG. ENGINEER No. 3892 REG. SURVEYOR No. 10516

FILED MAY 1 6 2014

PEGGY HOLINGA KATONA LAKE COUNTY AUDITOR 45.20-15-200-03-000-012

2014-028164 2614-028164

S 89°41'06" E 393.05' 42.41' 82.9' OCUITICITE 13 NOT OFFICIAL!

This Document is the property of

the Lake County Recorder! PT. NE1/4 SEC. 15-33-8

"SIEGMUND AND KAREN KREBS" DOC. NO. 774099

SURVEYOR'S REPORT

In accordance with Title 865, Article 1.0, Chapter 12, Section 1 through 34 of the Indiana Administrative Code, the following observations and opinions are submitted regarding the various uncertainties in the location of the lines and corners established on this survey as a result of:

The following documents were used in the course of this survey: 1. The deed of record of the parent parcel to the hereon surveyed original parcel. 2. This survey was performed without the benefit of a Title Commitment. The description on the hereon drawn plat was written by Krull Surveying for

The following monuments were used for this survey: 1. The county monument at the Northeast corner of Section 15.

5. A iron rod at the South 1/4 corner of Section 15.

the conveyance of the described parcel.

2. The county monument at the Southeast corner of Section 15.

4. A MAG nail at the Northwest corner of Section 15.

3. A stone with chiseled "X" at the Southwest corner of Section 15.

Uncertainties resulting from occupation lines: No apparent uncertainties in possession were observed.

Availability and condition of reference monuments:


were found at or near grade.


Discrepancies due to record descriptions: No apparent uncertainties resulted from the record descriptions.

The Relative Positional Accuracy (due to random errors in measurements) of this survey is within that allowable for an Urban Survey (0.07 feet plus 50 ppm) as defined in IAC 865.

The monuments were in good condition and appeared undisturbed and

NOTE: According to FIRM Community-Panel 18089C0375E. dated January 18, 2012, the above described parcel is in Zone "X" (unshaded).







SE. CORNER SE1/4 SEC.15

STATE OF INDIANA)
COUNTY OF LAKE) THIS IS TO CERTIFY THAT I HAVE SURVEYED THE ABOVE DESCRIBED PROPERTY ACCORDING TO THE OFFICIAL RECORDS AND THAT THE PLAT HEREON DRAWN CORRECTLY REPRESENTS SAID SURVEY.

KEVIN A. KRULL, REG. LAND SURVEYOR NO. 20100075

EXPLANATIONS NO DIMENSIONS SHOULD BE ASSUMED BY SCALE MEASUREMENTS UPON THE PLAT NOTE - CONTRACTORS OR BUILDERS SHOULD BE NOTIFIED TO CAREFULLY TEST AND COMPARE ON THE GROUND THE POINTS, MEASUREMENTS, ETC..., AS NOTED IN THIS CERTIFICATE, WITH THE STAKES, POINTS, ETC...,

DIFFERENCE BETWEEN THE SAME TO THE SURVEYOR, THAT MISUNDERSTANDING, DISPLACEMENT OF POINTS, ETC..., MAY BE CORRECTED BEFORE DAMAGE IS DONE. PT. NE 1/4 SEC. 15-33-8 CD: K3 FILE: 14-41.* (\\Server\d\Krull Surveying\Work\14-41.dwg) KK FIELD BOOK NO. Notes

ORDERED BY Karen Krebs PLATNO.

GIVEN ON THE PROPERTY, BEFORE BUILDING ON THE SAME, AND AT ONCE REPORT ANY SEEMING OR APPARENT