KRULL & SON

000022

LANE

ROBERT A. KRULL REG. ENGINEER No. 3892 REG. SURVEYOR No. 10516

2

05

 \bigcirc

 \mathcal{C} 60

ENGINEERS AND SURVEYORS

ESTABLISHED 1914 P.O. BOX 422 206 MAIN STREET HOBART, INDIANA 46342 OFFICE PHONE 219-947-2568 2005 003601

PLAT OF SURVEY

NAME OF OWNER: Gayle Brannon

STREET ADDRESS:

KEY 25-15-36

DESCRIPTION OF PROPERTY: Part of the Northwest 1/4 of the Southeast 1/4 of Section 26, Township 34 North, Range 9 West of the 2nd P.M., in Lake County, Indiana described as follows: Commencing at the Southwest corner of the North 3/4 of said 1/4, 1/4 Section: thence South 00°00'00" West along the West line of the Northwest 1/4 of the Southeast 1/4 of said Section, 38.00 feet to the point of beginning; thence continuing South 00°00'00" West along said West line, 110.00 feet; thence South 89°27'33" East parallel to the South line of North 3/4 of said 1/4, 1/4 Section, 160.00 feet; thence North 00°00'00" East parallel to the West line of the Northwest 1/4 of the Southeast 1/4 of Section 26, 110.00 feet; thence North 89°27'33" West parallel to said South line, 160.00 feet to the point of beginning, containing 0.404 acres, more or less.

FILED

JAN 18 2005

STEPHEN R. STIGLICH LAKE COUNTY AUDITOR

NOTE: According to FIRM Community-Panel 180127-0002-B dated March 5. 1982, the above described parcel is in Zone "C"

1,38TH SW COR. N.3/4 NW1/4, SE1/4 SEC. 26-34-9 SOUTH LINE NORTH 3/4, NW 1/4. 38.00 兄氏区 M 30.00 **County Recorder!** DRIVEWAY GARAGE 26-34 55.6 回一回 DECK 公全区 LINE S 30.00 S 89'27'33" E 160.00 0 SURVEYOR'S REPORT IN ACCORDANCE WITH TITLE 865, ARTICLE 1.0, CHAPTER 12, SECTION 1 THROUGH 34 OF THE INDIANA ADMINISTRATIVE CODE, THE FOLLOWING OBSERVATIONS AND OPINIONS ARE SUBMITTED REGARDING THE VARIOUS UNCERTAINTIES IN THE LOCATION OF THE LINES AND CORNERS ESTABLISHED ON THIS SURVEY AS A RESULT OF THE FOLLOWING DOCUMENTS WERE USED IN THE COURSE OF THIS SURVEY 1. A PLAT OF SURVEY DATED MARCH 20, 1908 BY J. B. MURPHY OF THE WEST 1/2 OF THE SE 1/4 OF SECTION 26, TOWNSHIP 34 NORTH, RANGE 9 WEST OF THE 2ND P.M. THE FOLLOWING MONUMENTS WERE USED FOR THIS SURVEY:

1. VARIOUS PIPE AND ANGLES WERE FOUND WHICH APPEARED TO AGREE WITH OCCUPATION

AVAILABILITY AND CONDITION OF REFERENCE MONUMENTS: THE REFERENCE MONUMENTS WERE IN GOOD CONDITION AND APPEARED UNDISTURBED AND WERE FOUND AT OR NEAR GRADE.

UNCERTAINTIES RESULTING FROM OCCUPATION LINES: NO APPARENT UNCERTAINTIES IN POSSESSION WERE OBSERVED.

OF THE PARCELS TO THE NORTH.

DISCREPANCIES DUE TO RECORD DESCRIPTIONS: NO APPARENT UNCERTAINTIES RESULTED FROM THE RECORD DESCRIPTIONS.

THE THEORETICAL UNCERTAINTY (DUE TO RANDOM ERRORS IN MEASUREMENT) OF THE SUBJECT TRACT ESTABLISHED THIS SURVEY IS WITHIN THE SPECIFICATIONS FOR A CLASS B SURVEY 0.25 FEET +/-, AS DEFINED IN IAC 865.

EXPLANATIONS

NO DIMENSIONS SHOULD BE ASSUMED BY SCALE MEASUREMENTS UPON THE PLAT NOTE - CONTRACTORS OR BUILDERS SHOULD BE NOTIFIED TO CAREFULLY TEST AND COMPARE ON THE GROUND THE POINTS, MEASUREMENTS, ECT., AS NOTED IN THIS CERTIFICATE, WITH THE STAKES, POINTS, ECT., GIVEN ON THE PROPERTY, BEFORE BUILDING ON THE SAME, AND AT ONCE REPORT ANY SEEMING OR APPARENT DIFFERENCE BETWEEN THE SAME TO THE SURVEYOR, THAT MISUNDERSTANDING, DISPLACEMENT OF POINTS, ECT., MAY BE CORRECTED BEFORE DAMAGE IS DONE.

PAGE

PT. NW1/4, SE1/4 SEC. 26-34-9 Notes FIELD BOOK NO.

DISK: F-275 FILE: 05-0021.*

ORDERED BY GAYLE BRANNON PLAT NO.

AN COMP SCALE: 1" = 20' - 00" STATE OF INDIANA) SS: COUNTY OF LAKE)

HOBART, INDIANA January 13, 2005

THIS IS TO CERTIFY THAT I HAVE SURVEYED THE ABOVE DESCRIBED PROPERTY ACCORDING TO THE OFFICIAL RECORDS AND THAT THE PLAT HEREON DRAWN CORRECTLY REPRESENTS SAID SURVEY.