KEVIN A. KRULL REG. SURVEYOR No. 20100075

2015 060462

2015 SEP -4 PM 1:5

27/91

described as follows: The Easterly 145.13 feet of said Lot 9, excepting therefrom the Southerly 14.2 feet thereof, by parallel line, and excepting therefrom the following: Beginning at a point on the North line of Lot 9, a distance of 12.0 feet; thence North and parallel with the East line of Lot 9, a distance of 51.8 feet to the North line of Lot 9; thence East a distance of 12.0 feet along the North line to the point of beginning. (Document No. 2008-025124)

Parcel 2: The Southerly 14.2 feet of the Easterly 133.13 feet by parallel lines of Lot Numbered 9 as shown on the recorded plat of the Original Town (now city) of Hobart, recorded in Miscellaneous Record "D", page 423, in the Office of the Recorder of Lake County, Indiana. (Document

FILED

SEP 0 4 2015

JOHN E. PETALAS

LAKE COUNTY AUDITOR

45-09-32-152-020.000-018

SURVEYOR'S REPORT

In accordance with Title 865, Article 1.0, Chapter 12, Section 1 through 34 of the Indiana Administrative Code, the following observations and opinions are submitted regarding the various uncertainties in the location of the lines and corners established on this survey as a result of:

The following documents were used in the course of this survey:

1. The recorded subdivision plat of the Original Town of Hobart. 2. A Plat of Legal Survey of the NW 1/4 of Section 32-36-7, Survey book 4, page 8 and 9, which includes the Original Town of Hobart. 3. Numerous surveys by Krull and Son of parts of Lots 6 through 10 in

The following monuments were used for this survey:

the Original Town of Hobart.

1. Monuments found or set from previous Krull and Son surveys in the Original Town of Hobart.

2. Iron rods shown as set hereon are 5/8 inch rebar, 24 inches long, with yellow surveyor identification cap stamped "Krull RLS 20100075".

Availability and condition of reference monuments: The monuments were in good condition and appeared undisturbed and were found at or near grade.

Uncertainties resulting from occupation lines: Apparent uncertainties in possession were observed as follows: 1. The building and appurtenances situated on the surveyed parcels

deviated from the surveyed deed lines as shown hereon.

Discrepancies due to record descriptions: No apparent uncertainties resulted from the record descriptions.

The Relative Positional Accuracy (due to random errors in measurements) of this survey is within that allowable for a Suburban Survey (0.13 feet plus 100 ppm) as defined in IAC 865.

BITUMINOUS PAVEMENT

EXPLANATIONS

NO DIMENSIONS SHOULD BE ASSUMED BY SCALE MEASUREMENTS UPON THE PLAT NOTE - CONTRACTORS OR BUILDERS SHOULD BE NOTIFIED TO CAREFULLY TEST AND COMPARE ON THE GROUND THE POINTS, MEASUREMENTS, ETC..., AS NOTED IN THIS CERTIFICATE, WITH THE STAKES, POINTS, ETC... GIVEN ON THE PROPERTY, BEFORE BUILDING ON THE SAME, AND AT ONCE REPORT ANY SEEMING OR APPARENT DIFFERENCE BETWEEN THE SAME TO THE SURVEYOR, THAT MISUNDERSTANDING, DISPLACEMENT OF POINTS, ETC.., MAY BE CORRECTED BEFORE DAMAGE IS DONE.

ORIGINAL TOWN OF HOBART CD: K1 FILE: 15-195.* (\\Server\d\Krull Surveying\Work\15-195.dwg) KK~WW~KK

FIELD BOOK NO. Notes PAGE 101 4 121 ORDERED BY Scott Frey PLAT NO. Sub desc dr.

