CEDAR LAKE

GINA PIMENTEL RECORDER

STATE OF INDIANA LAKE COUNTY
RECORDED AS PRESENTED

GRAPHIC SCALE

(IN FEET) LINCH = 20FT

15' WIDE ABANDONED RIGHT OF WAY OF CHICAGO, INDIANAPOLIS AND LOUISVILLE RAILWAY

(8514 W)

SUBJECT PARCEL

2023-032117

1:42 PM 2023 Nov 29

COMPANY'S NORTH LEG OF THE SOUTH CEDAR LAKE WYE

LOT 6

LAKE COUNTY, INDIANA

LOT 7

1 PAGE 4 1

FILE

NOV 2 9 2023

PEGGY HOLINGA KATONA LAKE COUNTY AUDITOR

PLAT OF SURVEY

SUBJECT PARCEL DESCRIPTION:

LOTS 7, 8, AND 9 IN SHADY BEACH WYE ADDITION TO CEDAR LAKE, INDIANA, AS PER PLAT THEREOF, RECORDED IN PLAT BOOK 26, PAGE 80, IN THE OFFICE OF THE RECORDER OF LAKE COUNTY, INDIANA: AND ALL THAT PART OF THE NOW ABANDONED RIGHT OF WAY OF THE CHICAGO, INDIANAPOLIS AND LOUISVILLE RAILWAY COMPANY'S NORTH LEG OF THE SOUTH CEDAR LAKE WYE LYING NORTHEASTERLY OF THE NORTHEASTERLY LINES OF THE SOUTH PORTION OF LOTS 7, 8, AND 9 OF SHADY BEACH WYE ADDITION TO CEDAR LAKE AND SOUTH OF THE SOUTHWESTERLY LINES OF THE NORTH PORTION OF LOTS 7, 8, AND 9 OF SHADY BEACH WYE ADDITION TO CEDAR LAKE AND LYING BETWEEN THE NORTHWESTERLY LINE OF SOUTH PORTION OF SAID LOT 9 EXTENDED TO INTERSECT THE SOUTHWESTERLY CORNER OF THE NORTH PORTION OF SAID LOT 9 AND THE SOUTHEASTERLY LINE OF THE SOUTH PORTION OF SAID LOT 7 EXTENDED TO INTERSECT THE SOUTHEASTERLY CORNER OF THE NORTH PORTION OF SAID LOT 7, IN LAKE COUNTY,

SURVEYOR'S REPORT:

This Plat represents a Retracement Survey of: see the "Subject Parcel Legal Description" section of this Plat of Survey.

This Survey is based on the locations of called-for and uncalled-for monuments found at or near the corners of the subject parcel, and at or near the corners of adjacent parcels as shown herein.

- patiest, and as time the Unifies of adjacem parces as some network.

 Reference was made to the following:

 1. A Plat of Survey of the Easterty Adjoining Property performed by Glen E. Boren (R.L.S. No. 20000006), dated May 7, 2021
 and under Job No. \$21-611.
- A Surveyor's Legal Survey of the Easterly and Westerly Adjoining Properties performed by Samuel E. Brownsten (R.L.S. No. 1754), dated December 24, 1957, under Book No. 220, Pages 61-64.
- N. In Proceedings 24, 1957, intellection 420, register of 1958.

 The record Warranty Deed of 10 7 in Shady Beach Wye Add, under an illegible Instrument No., recorded May 12, 1971 in the Office of the Recorder of Lake County, Indiana.

 4. Plat of Survey of 105 8 and 9 in Shady Beach Wye Add., performed by Alfred P. Torrenga (R.L.S. No. 10360), dated September 27, 1971 and under Job No. 3333.
- 5. The record Subdivision Plat of Shady Beach Wye Addition to Cedar Lake, Indiana, as per plat thereof, recorded in Plat
- The record Subdivision Plat or Snady select Wye Acotion to Cedar Lake, Incidiana, as per plat mereor, recorded in Plat Book 26, Page 80, in the Office of the Recorder of Lake County, Indiana.
 The record Warranty Deed of lots 8 and 9 in Shady Beach Wye Add, under Instrument No. 2022-0512428, dated March 23, 2022 in the Office of the Recorder of Lake County, Indiana.

All future reference to the above described documents in this Surveyor's Report will make use of the number assigned to said

The purpose of this Plat of Survey was to perform a retracement survey of the above described parcels of land. A search was performed throughout the surveyed parcel and surrounding parcels of land for boundary corner monuments and the results of said search are shown hereon. The basis of bearings for this survey was the bearings on the lines taken from reference plat 1. I was able to establish the Southeasterly line of the subject parcel based on reference plat 1. The Northeasterly, the Northwesterly and the Southwesterly lines were established based on reference plat 2 as shown hereon.

A.) AVAILABILITY OF MONUMENTS:

Uncertainties in Monument locations are noted. Unless otherwise stated, found monuments were undisturbed, in good condition, of unknown origin, and at or near grade.

B.) OCCUPATION AND POSSESSION

The apparent uncertainties resulted due to occupation or possession lines is shown in detail along the Northwesterly and terly lines of the subject parcel being existing fence lines

C.) CLARITY OR AMBIGUITY OF RECORD DESCRIPTIONS:

The apparent ambiguity in the record description of the subject parcel is reference plat 5 which has missing dimensions, on angles and no bearings to follow.

D.) RELATIVE POSITIONAL ACCURACY (due to random errors in measurements)

erformed met the requirements of a SUBURBAN SURVEY according to title 865 IAC 1.1 - 12 et seq. The tive positional accuracy is not less than 0.13 feet (40 millimeters) plus 100 parts per million for set monuments.

2023-032117

STATE OF INDIANA } §

I, JOHN STUART ALLEN, A REGISTERED LAND SURVEYOR IN THE STATE OF INDIANA, LICENSE #299000II, CERTIFY THAT THE ABOVE DESCRIBED SURVEY WAS PREPARED WHOLLY BY ME OR UNDER MY DIRECT SUPERVISION IN ACCORDANCE WITH RULE 12 OF TITLE 865, ARTICLE I OF THE INDIANA ADMINISTRATIVE CODE FOR BOUNDARY/RETRACEMENT

TORRENGA SURVEYING, LLC.

JOHN-STUART ALLEN - Registered Land Surveyor No. LS29900011

The information may or may not reference the most current deed or record or the most current status or title for that parcel. AUGUST 15, 2022 PLAT OF SURVEY LOTS 7-9 IN SHADY BEACH WYE ADDITION 8510 & 8514 W. 146TH AVENUE IN THE TOWN OF CEDAR LAKE

BYI.PYI

LOT 8

CONCRETE

PROFESSIONAL LAND SURVEYORS 907 RIDGE ROAD, MUNSTER, INDIANA 46321

TORRENGA SURVEYING, LLC

WEBSITE: WWW.TORRENGA.COM



STUART

No.

LS29900011

STATE OF

CLIENT(S): ANITA TOROK JOB NO: 2022-0401 SCALE: 1"=20" DRAWN.

mensions on this plat are expressed in feet and decimal parts thereof, and are measured values, unless otherwise noted.

2. This survey does not purport to show data concerning the existence, size, depth, condition, capacity or location of any utilities, structures and/or features, other than those observed and shown. Prior to any excavation contact the local utility facilities or call (811) for field locations of underground utility lines.

3. This survey does not address the existence, if any, of items that would require an interpretation by the surveyor, (I.E. compliance with all zoning requirements) existence of items beyond the qualification of survey (I.E. wetlands, hazardous material) and items not readily visible during a reasonable inspection of site (past cemeleries,

Parcels identified by title description or record references as per 865 IAC 1-12-13-(11) are obtained from County Auditor's Office and/or Recorder's Office and are not certified.

landfills, and mineral rights).

EGEND:

PIPELINE MARKET

CATCH BASIN/INLET MANHOLE

POWER POLE

WELL HEAD POWER POLE ANCHOR

LIGHT POLE STUR MARKER ELECTRIC METER

GAS METER

FOUND IRON PIPE

FOUND IRON BAR

FOUND MAG NAIL

SET 5/8" IRON REBAR W/"ALLEN 29900011" I.D. CAP

OVERHEAD LINES

EXISTING FENCE

*

E(S)

⊗G

@FIP